

# Intel® High Definition Audio HDMI Driver

Production Version 5.10.0.1046

## Release Notes

---

*August 29, 2008*

*Microsoft Windows\* XP  
Microsoft Windows\* XP 64*

### INTEL CONFIDENTIAL

**DISCLAIMER:** Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty relating to sale and/or use of Intel products, including liability or warranties relating to fitness for a particular purpose, merchantability or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, lifesaving, or life-sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

\* Other names and brands may be claimed as the property of others.  
Copyright © Intel Corporation 2008

This document contains information on products in the design phase of development. The information herein is subject to change without notice. Do not finalize a design with this information.

---

## Revision History

Date	Driver Revision	Build Number
September 27, 2007	Alpha 5.10.0.1032	1032
April, 11 2008	Production Candidate 5.10.0.1038	1038
April 18, 2008	Production Candidate 5.10.0.1041	1041
May 16, 2008	Production Candidate 5.10.0.1042	1042
May 20, 2008	Production Version 5.10.0.1042	1042
July 1, 2008	Production Version 5.10.0.1044	1044
August 29, 2008	Production Version 5.10.0.1046	1046

## High Definition Audio Function Driver

The Intel High Definition Audio HDMI Driver contains support for the following Intel Chipsets:

- Intel(R) G43 Express Chipset
- Intel(R) G45 Express Chipset
- Intel(R) G33 Express Chipset
- Intel(R) G35 Express Chipset
- Intel(R) G965 Express Chipset
- Intel(R) Q33 Express Chipset
- Intel(R) Q35 Express Chipset
- Intel(R) Q963 Express Chipset
- Intel(R) Q965 Express Chipset
- Mobile Intel(R) GL960 Express Chipset
- Mobile Intel(R) GLE960 Express Chipset
- Mobile Intel(R) GM965 Express Chipset
- Mobile Intel(R) GME965 Express Chipset
- Mobile Intel(R) GL40 Express Chipset
- Mobile Intel(R) GM45 Express Chipset
- Mobile Intel(R) GM47 Express Chipset

## Known Issues

Reference No.	Description	Affected Component(s)	Affected OS(s)	Affected Project(s)
2787459	HDMI audio has some pop sound at music start up in selected monitor	Audio	Windows XP	Mobile Intel® 45 Series Chipset Family
2787747	System occur BSOD 0x8E in test display switching	Audio	Windows XP	Mobile Intel® 45 Series Chipset Family

## Issues Resolved

Issues Resolved in Build 1046				
Reference No.	Description	Affected Component(s)	Affected OS(s)	Affected Project(s)
<b>Bug ID:</b> 2742939	BSOD happens during s3/s4 resume with HDMI connected status.	Audio	Windows XP	Mobile Intel® 45 Series Chipset Family

**Root Cause**

Attempt to acquire mutex from invalid IRQL level.

Issue is fixed by removing the mutex.

**Bug ID:**  
2742559

BSOD while resume  
from S3 with extended  
mode(HDMI)

Audio

Windows XP

Mobile Intel® 45  
Series Chipset  
Family

**Root Cause**

Attempt to acquire mutex from invalid IRQL level.

Issue is fixed by removing the mutex.